

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service


Measurements

Sp1	95.6 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 9:24:57 PM



FLIR0911.jpg

FLIR E8xt Wifi

639148831

5/15/2024 9:24:57 PM



FLIR0911.jpg

FLIR E8xt Wifi

639148831

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None
North Side Electrical Service


Measurements

Sp1	90.4 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 7:44:08 PM




FLIR0681.jpg

FLIR E8xt Wifi

639148831

5/15/2024 7:44:08 PM



FLIR0681.jpg

FLIR E8xt Wifi

639148831

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service


Measurements

Sp1	95.1 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 7:44:15 PM



5/15/2024 7:44:15 PM



Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service

Electrical Equipment Infrared Inspection Report


Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service

Measurements


Sp1	79.0 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %



2/2/2024 1:43:09 AM



Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service

Measurements

Sp1	97.6 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 9:26:38 PM




FLIR0913.jpg

FLIR E8xt Wifi

639148831

5/15/2024 9:26:38 PM



FLIR0913.jpg

FLIR E8xt Wifi

639148831

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service


Measurements

Sp1	97.0 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 9:27:08 PM



FLIR0915.jpg

FLIR E8xt Wifi

639148831

5/15/2024 9:27:08 PM



FLIR0916.jpg

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service


Measurements

Sp1	95.7 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 9:27:15 PM




FLIR0917.jpg

FLIR E8xt Wifi

639148831

5/15/2024 9:27:15 PM



FLIR0917.jpg

FLIR E8xt Wifi

639148831

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None
North Side Electrical Service

Measurements

Sp1	96.5 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 9:27:25 PM




FLIR0919.jpg

FLIR E8xt Wifi

639148831

5/15/2024 9:27:25 PM



FLIR0919.jpg

FLIR E8xt Wifi

639148831

Electrical Equipment Infrared Inspection Report

Project : 2186 W 60 St. Hialeah Florida
Severity : None North Side Electrical Service


Measurements

Sp1	99.1 °F
-----	---------

Parameters

Emissivity	0.95
Refl. temp.	68 °F
Distance	3.3 ft
Atmospheric temp.	68 °F
Ext. optics temp.	68 °F
Ext. optics trans.	1
Relative humidity	50 %

5/15/2024 9:18:49 PM



FLIR0905.jpg

FLIR E8xt Wifi

639148831

5/15/2024 9:18:49 PM



FLIR0905.jpg

FLIR E8xt Wifi

639148831